

3. SERVICE 1 SERVICE 0000
TV9-KANNADA

Receiver TT1260

S2 LOCKED 188 TID 00001
BITRATE 4.50 Mbits/s

260

S2 PV BER -1 -3 -5
QUALITY 1.0 E-8 [|||||] [|||||] [|||||] [|||||]

iver TT1260

1.3
QUALITY

C/N
+15.8 dB

Receiver TT1260

1.4
QUALITY

C/N MARGIN
+10.4 dB

Receiver TT1260

QUALITY

SIG LVL -70
-38 dBm  -20

er TT1260

